

No Ream King Pin Kits



| <u>Part #</u> | <u>Size</u> | <u>Application</u> | <u>OEM Ref #</u> | <u>Price</u> |
|---------------|-----------------|--|------------------|--------------|
| 308-216 | 1.99" X 11.21" | FL931, 933, 941, 943 & 951 | R200198 | \$328.86 |
| 308-231 | 1.625" X 7.47" | Eaton / Rockwell / Mack | 301SQ47CP1 | \$232.55 |
| 308-232 | 1.794" x 10.4" | FF931, 932, 933, 941, 942, 943, 944 / FA223, 226, 227 / 02ARA | FAK4555 | \$255.88 |
| 308-249 | 1.609" X 9.66" | I108, 120, 132, 120S, 90 / FA118, 127, 139, 242, 248, 309, 329, 336 - 343 | 588808C91 | \$172.58 |
| 308-262 | 1.794" X 10.07" | Ford CF600, 700, 800 / CFT800 | 9HZ3111A | \$276.65 |
| 308-268 | 1.359" X 8.07" | D800F/W, I60S, 80, 80S / 02ADA | 1660271C91 | \$138.27 |
| 308-274 | 1.625" X 9.2" | EFA12, 12F4, 13F5 / 02250 | FAK4583 | \$268.31 |
| 308-276 | 1.921" X 9.87" | I100S, 100SA, 120S / 02ADA / 02ADL / 02ADD / 02ADN / 02ADG | 1668411C91 | \$320.39 |
| 308-277 | 2.046" X 10.12" | I140S, 140S/SG, 120W, 132SG / 02ADE / 02ADG | 1668412C91 | \$274.56 |
| 308-279 | 1.2" X 6.35" | Chevy P20, P30, P3500 / F050 | 15584736 | \$131.25 |
| 308-283 | 1.872" X 9.97" | FH4 / EFA18F3 / 20F4 / 22T2-T5 / 24T2-T5 | 329433 | \$420.35 |
| 308-284 | 1.794" x 10.4" | FF931, 932, 941, 942, 961 / 02ARA / FA223, 226, 227 / 02223 / 02227 / FD961 / MFS10 / MFS12 | 1665531C91 | \$276.14 |
| 308-286 | 1.433" X 8.25" | Ford B, F & FT Series | E9HZ3111C | \$178.83 |
| 308-297 | 1.794" X 9.05" | E1000I-W, 1200I-W, 1201W, 1320I-W / 02AED / 02AEG | 328342 | \$298.41 |
| 308-305 | 1.872" X 9.07" | E1002I-W, 1202I-W, 1322I-W, 1462I-W | 328347 | \$276.89 |
| 308-317 | 1.794" X 8.84" | FF981, 982, 983, 984, 986 / MFS12, 13 | R201419 | \$308.96 |
| 308-318 | 1.35" X 8.07" | D600F-N, 700N, 800F/W, 850FW | 329182 | \$200.76 |
| 308-331 | 1.794" x 10.4" | MFS13 / MFS14 / FG931 | R201319 | \$276.99 |

Please call for varieties not shown here.

*Bushing requires tool for proper installation, or we can install bushing.