

New Shoe Box Kits



<u>Part #</u>	<u>FMSI#</u>	<u>Size</u>	<u>Rating</u>	<u>Application</u>	<u>Price</u>
SB1308ES21P	1308	15 X 4	21K PREM	EATON	\$47.76
SB1308ES23S	1308	15 X 4	23K STD	EATON	\$51.30
SB1308ES23P	1308	15 X 4	23K PREM	EATON	\$58.05
SB1308Q21P	1308	15 X 4	21K PREM	MERITOR Q	\$64.45
SB1308Q23S	1308	15 X 4	23K STD	MERITOR Q	\$57.00
SB1308Q23P	1308	15 X 4	23K PREM	MERITOR Q	\$66.74
SB1443ES23S	1443	15 X 4	23K STD	EATON ES	\$58.42
SB1443ES23P	1443	15 X 4	23K PREM	EATON ES	\$65.52
SB4311ES23S	4311	16.5 X 7	23K STD	EATON ES	\$68.36
SB4311ES23P	4311	16.5 X 7	23K PREM	EATON ES	\$79.60
SB4515Q23S	4515	16.5 X 7	23K STD	MERITOR Q	\$53.57
SB4515Q23P	4515	16.5 X 7	23K PREM	MERITOR Q	\$59.99
SB4515X23S	4515	16.5 X 7	23K STD	FRUEHAUF XEM	\$62.86
SB4515X23P	4515	16.5 X 7	23K PREM	FRUEHAUF XEM	\$72.43
SB4707Q23S	4707	16.5 X 7	23K STD	MERITOR Q	\$55.39
SB4707Q23P	4707	16.5 X 7	23K PREM	MERITOR Q	\$62.47
SB4709ES2-23S	4709	16.5 X 7	23K STD	EATON ES2	\$60.90
SB4709ES2-23P	4709	16.5 X 7	23K PREM	EATON ES2	\$70.31
SB4711Q23S	4711	16.5 X 8.62	23K STD	MERITOR Q	\$65.70
SB4711Q23P	4711	16.5 X 8.62	23K PREM	MERITOR Q	\$74.89
SB4715Q23S	4715	16.5 X 6	23K STD	MERITOR Q	\$64.12
SB4715Q23P	4715	16.5 X 6	23K PREM	MERITOR Q	\$71.75
SB4725ES2-23S	4725	16.5 X 6	23K STD	EATON ES2	\$69.82
SB4725ES2-23P	4725	16.5 X 6	23K PREM	EATON ES2	\$84.12

Please call for varieties not shown here.