




Hendrickson Rear Suspension - HAULMAAX® Bolster Spring



Call us if you can't find or identify the part you need

Hendrickson Rear Suspension - HAULMAAX® Bolster Spring

| | | | | | |
|---|-----------|---|------------|----------|---|
| 1 | 338-2288 | Bracket; Outboard Frame | 64595-1 | \$189.26 | Western Star/Paccar; 34" Frame Width; 16.5" Saddle Height |
| 1 | 338-2289 | Bracket; Outboard Frame | 64636-2 | \$208.01 | Freightliner; 34.3"-34.5" Frame Width; 17.5" Saddle Height |
| 1 | 338-2290 | Bracket; Outboard Frame | 64595-101 | \$211.02 | International; 34.12"-34.25" Frame Width; 16.5" Saddle Height |
| 1 | 338-2291 | Bracket; Outboard Frame | 64595-104 | \$211.02 | International; 34.68"-34.94" Frame Width; 16.5" Saddle Height |
| 1 | 338-2292 | Bracket; Outboard Frame | 64595-3 | \$210.11 | Oshkosh; 34" Frame Width; 18.5" Saddle Height |
| 1 | 338-2325 | Bracket; Outboard Frame | 064636-003 | \$229.58 | Freightliner; 34.3"-34.5" Frame Width; 18.5" Saddle Height |
| 1 | See Chart | Bracket, Outboard Frame | Various | | Call For Identification & Price |
| 2 | 338-1931 | Assembly, Saddle; 400 Series; > 1/13/03 | 64642 | \$671.93 | Prior to 01/13/03 Retrofit Required |
| 2 | 338-1932 | Assembly, Saddle; 460 Series; > 1/13/03 | 64643 | \$619.41 | Prior to 01/13/03 Retrofit Required |
| 2 | SP | Kit, Saddle Retrofit; Prior to 1/13/03 | 57974-xxx | | Call For Identification & Price |
| 3 | 338-2293 | Bracket; Inboard Frame | 65078-1 | \$81.78 | CCC/Oshkosh; 34" Frame Width; 16.5" Saddle Height |
| 3 | 338-2294 | Bracket; Inboard Frame | 65078-3 | \$81.81 | Oshkosh/Autocar/CCC; 34" Frame Width |
| 3 | 338-2295 | Bracket; Inboard Frame | 65079-1 | \$81.76 | Paccar w/o Liner; 34"-34.75" Frame Width; 16.5" Ride Hgt |

Call us if you can't find or identify the part you need

| | | | | | |
|---|-----------|--|------------------------|----------|--|
| 3 | 338-2296 | Bracket; Inboard Frame | 65079-3 | \$85.70 | Paccar w/o Liner; 34"-34.5" Frame Width; 18.5" Ride Hgt |
| 3 | 338-2266 | Bracket; Inboard Frame | 060617-502 | \$69.27 | Freightliner 34.3"-34.5"& Western Star 34"Frame Width; 17.5" Saddle Height |
| 3 | See Chart | Bracket, Inboard Frame | Various | | Call For Identification & Price |
| 4 | SP | Spacer (If Equipped) | 60618-xxx | | Call For Identification & Price |
| 5 | 334-1727 | Kit, Service; Bolster Spring | 64179-2 | \$219.08 | HMX 400; R/B 334-2035 |
| 5 | 334-1845 | Kit, Service; Bolster Spring | 64179-37 | \$239.87 | Haulmax 460 |
| 6 | 334-2035 | Kit, Service; w/Wear Plate | 64179-49 | \$224.92 | HMX 400 |
| 6 | 334-2036 | Kit, Service; Bolster Spring w/Wear Plate | 64179-48 | \$236.62 | HMX 460 |
| 7 | 334-1719 | Plate, Wear | 64890 / 64179-5 | \$37.89 | |
| 8 | 334-1720 | Kit, Auxiliary Spring | 64179-4 | \$110.35 | Single Side Standard Replacement |
| 8 | 334-1968 | Kit, Service; Progressive Rate Auxiliary Spring | 65902-4 / 59310-047 | \$144.29 | Single Side Progressive Conversion |
| 8 | 334-2029 | Kit, Service; Progressive Load; Single | 60961-745 | \$120.94 | Single Side Progressive Replacement |
| 8 | 334-2031 | Kit, Service; Progressive Load; Tandem | 60961-747 | \$226.78 | Tandem Progressive Replacement or Conversion |
| 8 | 334-2030 | Kit, Service; Progressive Load; Tandem Weight Bias | 60961-746 | \$234.90 | Tandem Standard/Progressive Replacement |
| 9 | 334-1894 | Assembly, Spring; Auxiliary | 60314 | \$107.90 | Incl. in 334-1720 |
| 9 | MHS58948 | Assembly, Progressive Rate Spring | 67778 | \$81.58 | Incl. in 334-1968 |

Call us if you can't find or identify the part you need

| | | | | | |
|----|-------------|---|------------------------|----------|---|
| 10 | 338-1933 | Plate, Auxiliary Spring Contact | 59191-1 / 59191 | \$32.87 | |
| 11 | 338-1934 | Bracket, Auxiliary Spring | 59384 | \$27.32 | |
| 12 | 334-1728 | Shim, Auxiliary Spring; 1/4"Thk | 60791 | \$11.23 | |
| 13 | 334-1721 | Kit, Fastener; Saddle | 64179-38 / 64179-29 | \$111.83 | Incl. Necessary Hardware to Attach (2) Saddles |
| 14 | 334-1722 | Kit, Strap; Rebound | 64179-28 | \$41.75 | |
| 15 | 334-1634 | Strap, Rebound | 57878-3 | \$23.16 | |
| 16 | 334-1729 | Clip, Rebound Strap | 60612 | \$8.85 | |
| 17 | 334-1723 | Assembly, Bolt; 3/4"-16 x 6"Lg | | \$10.06 | |
| 18 | 341-60680-4 | Shock Absorber | 60680-4 | \$71.13 | 16 1/2" Saddle Hgt |
| 18 | 341-60680-5 | Shock Absorber | 60680-5 | \$72.13 | 17 1/2"-18 1/2" Saddle Hgt |
| 19 | 334-1724 | Assembly, Bolt; 5/8"-11 x 3-1/4"Lg | | \$7.10 | |
| 20 | 334-1725 | Kit, Retrofit; Shock Absorber | 64178-3 | \$636.95 | 16 1/2" Saddle Hgt |
| 20 | 334-1726 | Kit, Retrofit; Shock Absorber | 64178-4 / 64178-9 | \$518.69 | 17 1/2"-18 1/2" Saddle Hgt |
| 21 | 334-831 | Kit, Service; Bar Pin Bushing; Shim Type | 34013-88 | \$112.88 | Incl. Bar Pin Bushing, Alignment Shims & Mounting Hdwe. |
| 21 | 334-1957 | Kit, Service; Rotating Bar Pin Bushing; Shim Type | 34013-188 | \$156.67 | Incl. Bolts & Shims |
| 22 | 334-832 | Assembly, Bolt; 1"-8 x 6"Lg Grade 8 | 56659-5 | \$16.21 | Incl. Bolt, Lock Nut & Washers |
| 23 | 345-866 | Kit, Torque Rod; Straddlemount | 60218 | \$126.66 | Use 345-610 & 345-661 |
| 24 | 345-907 | Track Rod; 24.21"Lg | 62350-615 | \$157.99 | Other Lengths Available |
| 24 | 345-897 | Kit, Torque Rod; Straddle/Taper Pin | 60215 / 62350-xxx | \$148.52 | Use 345-610 & 345-681 |

Call us if you can't find or identify the part you need

| | | | | | |
|----|------------------------|--|----------------------|------------|---|
| 25 | 338-874 | Bracket, Track Rod Axle | 46868 | | Rockwell SQ100, SQHP, SL100; 4-5/8"x 5-1/4" Axles |
| | | | | \$328.59 | |
| 26 | 338-181 | Bracket, Track Rod/Frame | 22186 | \$15.40 | For 5/8" Bolts |
| 27 | 334-638 | Plate, Reinforcement | 45045-3 | \$17.35 | |
| 28 | 338-2115 | Assembly, Beam; 52" w/o Shocks | 64847-3 | \$1,125.77 | Incl. 334-381 Bushings |
| 28 | 338-2045 / 338-2048 | Assembly, Beam; 54" | 64847-1 / 64846-1 | \$1,141.75 | Incl. 334-831 Bushings |
| 28 | 338-2347 | Assembly, Walking Beam | 80226-1, | \$1,421.73 | Rotating End Bushings |
| 28 | 338-2435 | Assembly, Walking Beam | 80225-1, | \$1,411.63 | Rotating End Bushings |
| 28 | 338-2436 | Assembly, Walking Beam | 80227-2, | \$1,755.45 | Rotating End Bushings |
| 29 | 334-2229 | Kit, Service; Bolster & Load Spring; Tandem | 60961-712 | \$556.58 | Incl. (2) 334-2036, (1) 334-2029 |
| 30 | 338-2305 | Upper Shock Bracket | | \$16.64 | |
| 31 | 338-2406 | Rebound Support Angle | 60613, | \$10.24 | |
| 32 | 334-2120 | Aux Spring Contact Plate Kit | 57974-46 | \$44.39 | |
| 33 | 338-2405 | Aux Spring Spacer | 60874 | \$6.59 | |

Call us if you can't find or identify the part you need